

PHASE I ENVIRONMENTAL SITE ASSESSMENT



**SANDOVAL COUNTY
529 ACRES OF RURAL PROPERTY
SECTION 36, SANDOVAL COUNTY, NEW MEXICO**

JANUARY 7, 2025



Souder, Miller & Associates
Engineering ♦ Environmental ♦ Geomatics

5454 Venice Avenue NE, Suite D ♦ Albuquerque, NM 87113
505.299.0942 ♦ 877.299.0942 ♦ fax 505.293.3430 ♦ www.soudermiller.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

SANDOVAL COUNTY
529 ACRES OF RURAL PROPERTY
SECTION 36, SANDOVAL COUNTY, NEW MEXICO

JANUARY 7, 2025

Submitted to:

Dora M. Dominguez
Director of County Business & Economic Development
Sandoval County
P.O. Box 40
Bernalillo, NM 87004
505.697.7644
ddominguez@sandovalcountynm.gov

Prepared by:

Souder, Miller & Associates
5454 Venice Avenue NE, Suite D
Albuquerque, NM 87113
505-299-0942, office



Project Geoscientist: Mariah Kelly, REM
SMA Project # 1433990




Senior Geoscientist: Matthew A. Earthman, P.G.

Write a description for your map.

- Albuquerque Rocket Society Rio?



Property Boundary



Google Earth

Magazine Archives

July 1



Photo 51. Main arroyo of subject property western channel walls, looking northwest



Photo 52. Solid waste observed in main arroyo at interior of subject property in southeast portion, view to west



Photo 53. Solid waste piles observed in main arroyo in interior of subject property in southeast portion, looking southeast



Photo 54. Solid waste piles observed in main arroyo in interior of subject property in southeast portion, looking east



Photo 55. Solid waste piles observed on southwest corner of subject property, looking northeast



Photo 56. Solid waste piles observed on eastern portion of subject property, east of 20th St NW, looking west



Photo 57. Abandoned boat on eastern portion of subject property, east of 20th St NW, looking west



Photo 58. Burned material in interior of subject property in southeast portion, looking east



Photo 59. Burned structure in interior of subject property, east of 20th St NW in northeast portion, looking north



Photo 60. Burned structure in subject property, east of 20th St NW, looking southwest



Photo 61. Solid waste near burned structure, east of 20th St NW, looking northeast



Photo 62. Erosion control along northern boundary of subject property, looking southwest along King Blvd NW



Photo 63. Erosion control along northern boundary of subject property, looking southeast on King Blvd NW



Photo 64. Persons living on east adjoining property to the subject property at 33rd Ave NW, looking east